

### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	ıtfall Site I.D.	1b
APDES Tracking No.	AKR_06R0A	AB76		mple Illection Date & ne	8/23/2021 1404
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Runoff	Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.			
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Out	tfall	■Absent	□Present	□Other					
	Sample take	n in clea	ın, clear contair	er?	□Yes	□No				
	Sample insp	ected in	a well-lit area?		□Yes	□No	]			
	Visual Asses	sment [	Date and Time							
Ρ	rinted Name: '	Jeremy	Langton	Title: _	Engineering A	Assistant	t		_	
S	ignature:	from y	ngter							



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	utfall Site I.D.	3a
APDES Tracking No.	AKR_06R0A	AB76	Co	imple bllection Date & ne	8/23/2021 1442
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Runoff	Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.	'		
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
P	rinted Name: Jeremy	Langton	Title: <u> </u>	Engineering A	Assistant		
S	ignature: 🔎	Juzter					



### **MSGP 6.2**

Name of Facility	Fairbanks Interna	ational Airport	Οι	ıtfall Site I.D.	4b
APDES Tracking No.	AKR_06R0A	AB76	Co	mple Illection Date & ne	8/23/2021 1404
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	■ Yes	☐ No			
Type of Discharge (Check box)	Snowmelt Runoff	X Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.			
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	<b>■</b> Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	<b>■</b> Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	<b>■</b> Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contain	er?	■Yes	□No	
	Sample inspected in	a well-lit area?		■Yes	□No	
	Visual Assessment [	Date and Time		8/23/21 1404		
Р	rinted Name: Jeremy	Langton	Title:	Engineering A	Assistant	<u>t</u>
S	gnature: _ Any fun	ytin				



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Interna	ational Airport	Οι	utfall Site I.D.	5a
APDES Tracking No.	AKR_06R0A	NB76	Co	imple ollection Date & ne	8/23/2021 1320
Inspector Name(s)	Jeremy Lar	gton			
Weather Conditions/Notes	54°F, Rainir	ıg			
Discharge at Site? (Circle)	■ Yes	☐ No			
Type of Discharge (Check box)	Snowmelt Runoff	X Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.			
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	<b>■</b> Clear	□Cloudy	□Dark	
Floating Solids	<b>■</b> Absent	□Present		
Settled Solids	■Absent	□Present		
Suspended Solids	<b>■</b> Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other	
	Sample taken in clea	an, clear contain	er?	■Yes	□No
	Sample inspected in	a well-lit area?		■Yes	□No
	Visual Assessment [	Date and Time		8/23/21 1320	
Р	rinted Name: <u>Jerem</u> y	Langton	Title: _	Engineering A	Assistant
S	ignature:	Juzter			



#### **MSGP Quarterly Visual Assessment MSGP 6.2**

Fairbanks International Airport			utfall Site I.D.	5b	
AKR_06R0AB76			ollection Date &	8/23/2021 1408	
Jeremy Lar	gton				
54°F, Rainin	ıg				
■ Yes	☐ No				
Snowmelt Rainfall Runoff Runoff					
Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)	
Not practicable.					
None.					
	Jeremy Lan  54°F, Rainin  Yes  Snowmelt Runoff  Rainfall Duration (Days)  Not practica	Jeremy Langton  54°F, Raining  Yes No  Snowmelt Runoff Rainfall Quration (Days)  5  Not practicable.	AKR 06R0AB76 Sa Co Tin Jeremy Langton  54°F, Raining  Yes No  Snowmelt Rainfall Runoff Rainfall Duration (Days)  5 0.81  Not practicable.	AKR 06R0AB76 Sample Collection Date & Time  Jeremy Langton  54°F, Raining  I Yes No  Snowmelt Rainfall Runoff Rainfall Ouration (Days)  5 Not practicable.	

Observation	Description			Comments and/or Probable Source of Observed Contamination
Color	Clear	☐ Cloudy	☐ Dark	
Odor	■Absent	□Sewage	□Rotten Eggs	
Clarity	■Clear	□Cloudy	□Dark	
Floating Solids	■Absent	□Present		
Settled Solids	■Absent	□Present		
Suspended Solids	■Absent	□Present		
Foam	■Absent	□Present		
Oil Sheen	■Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other		
	Sample taken in clea	an, clear contain	er?	■Yes	□No	
	Sample inspected in	a well-lit area?		■Yes	□No	
	Visual Assessment [	Date and Time		8/23/21 1408		
Printed Name: Jeremy Langton Title			Title:	Engineering A	Assistant	
S	gnature: 🏻 🔎	Juzten				



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks Intern	ational Airport	Outfall	Site I.D.	6a
APDES Tracking No.	AKR_06R0AB76		Sampl Collec Time	e tion Date &	8/23/2021
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Runoff	Rainfall Runoff			
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81	6	Time Since	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.	•		
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□ Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
Р	rinted Name: Jeremy	Langton	Title: <u></u>	Engineering A	Assistant		
S	ignature:	Juzten					



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport			ıtfall Site I.D.	7d
APDES Tracking No.	AKR_06R0AB76			mple Ilection Date & ne	8/23/2021 1422
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.	•		
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
Р	rinted Name: Jeremy	Langton	Title: <u></u>	Engineering A	Assistant		
S	ignature:	Jungton					



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport		Οι	ıtfall Site I.D.	9a
APDES Tracking No.	AKR_06R0AB76			mple Illection Date & ne	8/23/2021 1415
Inspector Name(s)	Jeremy Lar	ngton			
Weather Conditions/Notes	54°F, Rainir	ng			
Discharge at Site? (Circle)	☐ Yes	■ No			
Type of Discharge (Check box)	Snowmelt Rainfall Runoff Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)
Reason if Sample Not Collected Within First 30 Min.	Not practica	ble.	<u>'</u>		
Additional Comments	None.				

Observation		Description		Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
P	rinted Name: Jeremy	Langton	Title: _	Engineering A	Assistant		
S	ignature: 🛷	luzter					



#### **MSGP Quarterly Visual Assessment MSGP 6.2**

Name of Facility	Fairbanks International Airport		Outfall Site I.D.		10	
APDES Tracking No.	AKR_06R0AB76			mple Ilection Date & ne	8/23/2021 1420	
Inspector Name(s)	Jeremy Lar	ngton				
Weather Conditions/Notes	54°F, Rainir	ng				
Discharge at Site? (Circle)	☐ Yes	■ No				
Type of Discharge (Check box)	Snowmelt Runoff	☐ Rainfall Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since	Prior Rainfall Event (Days)	
Reason if Sample Not Collected Within First 30 Min.	Not practicable.					
Additional Comments	None.					

Observation	Description			Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□ Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
Printed Name: Jeremy Langton Title:				Engineering A	Assistant	: :	
S	ignature:	Jungton					



### MSGP Quarterly Visual Assessment MSGP 6.2

Name of Facility	Fairbanks International Airport		Outfall Site I.D.		11	
APDES Tracking No.	AKR_06R0AB76		Sample Collection Date & Time		8/23/2021 1430	
Inspector Name(s)	Jeremy Lan	ngton				
Weather Conditions/Notes	54°F, Rainin	ng				
Discharge at Site? (Circle)	☐ Yes	■ No				
Type of Discharge (Check box)	Snowmelt Runoff	☐ Rainfall Runoff				
For Rainfall Discharge, Record Storm Event Data	Rainfall Duration (Days) 5	Rainfall (Inches) 0.81		Time Since 6	Prior Rainfall Event (Days)	
Reason if Sample Not Collected Within First 30 Min.	Not practicable.					
Additional Comments	None.					

Observation	Description			Comments and/or Probable Source of Observed Contamination
Color	☐ Clear	☐ Cloudy	☐ Dark	
Odor	□Absent	□Sewage	□Rotten Eggs	
Clarity	□Clear	□Cloudy	□Dark	
Floating Solids	□Absent	□Present		
Settled Solids	□Absent	□Present		
Suspended Solids	□Absent	□Present		
Foam	□Absent	□Present		
Oil Sheen	□Absent	□Present	□Smell	



	Stains at Outfall	■Absent	□Present	□Other			
	Sample taken in clea	an, clear contair	er?	□Yes	□No		
	Sample inspected in	a well-lit area?		□Yes	□No		
	Visual Assessment [	Date and Time					
Printed Name: Jeremy Langton Title:			Engineering A	Assistant			
S	ignature: Am	Juzten					